

# Test Report



September 20, 2018

Client: Peterson Energy  
Project: CHURCH 41B-25 PW  
Lab ID: 8931  
Date Samples Received: 9/13/2018

Sample Condition: Samples arrived intact and in appropriate sample containers.  
Samples were received within the temperature range specified  
in the test method(s) and/or with thermal preservation in  
process.

Comments:

Thank you for allowing eAnalytics Laboratory to provide laboratory services for you.

A handwritten signature in black ink, appearing to read "Chris Dieken".

Chris Dieken  
QA Manager

A handwritten signature in black ink, appearing to read "Todd Rhea".

Todd Rhea  
Lab Manager

## Chain of Custody

**eANALYTICS**  
LABORATORY

Chain of Custody Form

[illegible]

**eANALYTICS**  
LABORATORY

Client: Peterson Energy Lab ID: 8931

Project: CHURCH 41B-25 PW

Analysis: Total Dissolved Solids (TDS) Method: EPA160.1

Sample Name	TDS mg/L	Date		Lab ID
		Sampled	Analyzed	
CHURCH 41B-25 PW	1490	09/13/18	09/20/18	8931 1

**eANALYTICS**  
LABORATORY

Client: Peterson Energy

Lab ID: 8931

Project: CHURCH 41B-25 PW

Analysis: Anions

Method: EPA300.0

Sample Name	Chloride	Sulfate	Date	Date	Lab ID
	mg/L	mg/L	Sampled	Analyzed	
CHURCH 41B-25 PW	201	230	09/13/18	09/14/18	8931 1

**eAnalytics Laboratory**

4130 Clydesdale Parkway Loveland CO 80538