

Stormwater Inspection

February 7th, 2023

Operator: Verdad Resources LLC, #10651

Location ID: 483467

Inspection Document #: 709400014

Weld, CO

SENW 32 2N64W 6

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 1. Photo of wattle on Northwest corner sediment trap. Wattle need to be reset.

Photo 2. See photo 1 comments

Inspection Photos
Location Name: Kiwi 2920
Location ID: 483467



Photo 3. Photo of wattles on Southwest corner sediment trap. Wattle on top of berm not in sediment trap spillway. Wattle needs to be moved to spillway.



Photo 4. See Photo 3 comments