

Interim Reclamation & Stormwater Inspection

February 7th, 2023

Operator: Verdad Resources LLC, #10651

Location ID: 453512

Inspection Document #: 709400016

Weld, CO

SESE, 10 1N65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Johnson
Location ID: 439158



Photo 1. Photo of location sign at entrance of the pad.



Photo 2. Facing toward county road from location entrance. Evidence of tracking on to the pavement.

Inspection Photos
Location Name: Johnson
Location ID: 439158



Photo 3. Photo of dead trees on location.
Trees were planted as part of the surface use agreement
and must be maintained..



Photo 4. See photo 3 comments

Inspection Photos
Location Name: Johnson
Location ID: 439158



Photo 5. Photo of weed debris on the outside of the location fence



Photo 6. See photo 5 comments

Inspection Photos
Location Name: Johnson
Location ID: 439158



Photo 7. Photo of topsoil stockpile and reclaimed area, weed management is needed.



Photo 8. See photo 7 comments