

Interim and Stormwater Inspection

February 21, 2023

Operator: Extraction Oil & Gas , #10459

Location ID: 321379

Inspection Document #:709400023

Broomfield, CO

NENE, Section 2, 1S69W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simpson MD 2-1
Location ID: 321379



Photo 1. Photo taken of location sign at entrance of pad..



Photo 2. Photo taken location sign at tank battery.

Inspection Photos

Location Name: Simpson MD 2-1

Location ID: 321379



Photo 3. Photo taken of weeds on North side of location and access road.



Photo 4. See Photo 3 comments.



Inspection Photos

Location Name: Simpson MD 2-1

Location ID: 321379



Photo 5. Photo taken of downed perimeter fence of tank battery.



Photo 6. See Photo 5 comments.

