

Interim and Stormwater Inspection

February 21, 2023

Operator: Extraction Oil & Gas , #10459

Location ID: 321279

Inspection Document #:709400025

Broomfield, CO

NENE, Section 2, 1S69W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Photo taken of location sign at tank battery

Inspection Photos
Location Name: Arapahoe 61N69W
Location ID: 321279



Photo 2. Photo of weed on location.



Photo 3. See photo 2 comments.