

# Interim and Stormwater Inspection

February 21, 2023

Operator: Crestone Peak , #10633

Location ID: 322858

Inspection Document #:709400029

Weld, CO

SWSW, Section 33, 2N68W

Reed Wold

Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Photo 1. Photo taken of location sign at tank battery on location.



Inspection Photos  
Location Name: Oskarson E 1 Battery  
Location ID: 322858



**Photo 2. Photo taken facing north of stormwater leaving site causing reeling**



**Photo 3. Photo taken facing southwest of stormwater leaving site causing reeling**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400029



Inspection Photos  
Location Name: Oskarson E 1 Battery  
Location ID: 322858



**Photo 4. Photo taken facing west on location of reclaimed area.**

