

Interim Reclamation and Stormwater Inspection

February 28, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697504541

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing East. Photo illustrates trash being stored on location has mostly been removed and still requires additional cleanup.



Photo 2. Photo taken from the southeastern location, facing Northeast. See comments under Photo 1.

Note- weeds were observed along the eastern perimeter of location.

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 3. Photo taken from the wellheads, facing North. Photo illustrates unused equipment has been removed.



Photo 4. Photo taken of the northeastern location, facing Northeast. Photo illustrates the chemical container has been removed.

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 5. Photo taken from the northwestern location, facing North. See comments under Photo 4.



Photo 6. Photo taken from the western location, facing West. Photo illustrates stained soil/spill related to the compressor.

Note- it does not appear any action has been taken since the previous inspection.

Inspection Photos

Location Name: Little Lady 21/North Well Pad

Location ID: 462908



Photo 7. Photo taken from the western location. Photo illustrates a hose left hooked up has been disconnected.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504541