

Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334610

Location Name: BASS-67S93W/14SWNE

Inspection Document #: 702801311

Garfield County, CO

SWNE Section 14 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BASS-67S93W/14SWNE
Location ID: 334610



Photo 1. Photo taken from the entrance shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801311

Inspection Photos
Location Name: BASS-67S93W/14SWNE
Location ID: 334610



Photo 2. Photos show fluid released from a produced water/condensate tank drain.



Inspection Photos

Location Name: BASS-67S93W/14SWNE

Location ID: 334610



Photo 3. Photo shows a bull plug has been installed on a tank drain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801311

Inspection Photos
Location Name: BASS-67S93W/14SWNE
Location ID: 334610



Photo 4. Photo shows caps are installed on piping at the tank battery.