

# Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334635

Location Name: PARKER-67S93W/15NESE

Inspection Document #: 702801313

Garfield County, CO

NESE Section 15 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PARKER-67S93W/15NESE  
Location ID: 334635



**Photo 1.** Photo taken from the entrance shows an overview of the location.

Inspection Photos  
Location Name: PARKER-67S93W/15NESE  
Location ID: 334635



**Photo 2.** Photo shows a chemical tank that is in use per the Operator. The tank appears to have been hooked up however, it appears empty.



Inspection Photos  
Location Name: PARKER-67S93W/15NESE  
Location ID: 334635



**Photo 3.** Photo shows the tank battery. A tank battery sign has been installed.

