

Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334575

Location Name: ROSE RANCH-67S93W/15NWNE

Inspection Document #: 702801315

Garfield County, CO

NWNE Section 15 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROSE RANCH-67S93W/15NWNE
Location ID: 334575



+39.

3/3/23
+39.452902,-107.759064
352° N




Photo 1. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801315

Inspection Photos

Location Name: ROSE RANCH-67S93W/15NWN

Location ID: 334575



Photo 2. Photo shows wildlife protection BMPs to prevent entry into tank battery piping are absent.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801315

Inspection Photos
Location Name: ROSE RANCH-67S93W/15NWNE
Location ID: 334575



Photo 3. Photo shows interim areas.

