

# Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Well API #: 045-06943

Well Name: PARKER RANCH #10-9

Inspection Document #: 702801319

Garfield County, CO

NESE Section 10 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Well Name: PARKER RANCH #10-9  
Well API #: 045-06943



**Photo 1.** Photo shows a flowline riser which appears to be associated with plugged and abandoned well API #045-06943.