

Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334675

Location Name: ROSE RANCH-67S93W/10SWSE

Inspection Document #: 702801321

Garfield County, CO

SWSE Section 10 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ROSE RANCH-67S93W/10SWSE

Location ID: 334675



Photo 1. Photo taken from the entrance shows an overview of the location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321

Inspection Photos

Location Name: ROSE RANCH-67S93W/10SWSE

Location ID: 334675




Photo 2. Photo shows wildlife protection BMPs to prevent entry into separator piping are absent (circled). Photo also shows trash (arrows).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321

Inspection Photos

Location Name: ROSE RANCH-67S93W/10SWSE

Location ID: 334675



Photo 3. Photo shows wildlife protection BMPs to prevent entry into tank battery piping are absent.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321

Inspection Photos
Location Name: ROSE RANCH-67S93W/10SWSE
Location ID: 334675



Photo 4. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321

Inspection Photos
Location Name: ROSE RANCH-67S93W/10SWSE
Location ID: 334675

3/3/23
+39.456875,-107.756733
110° E



3/3/23
+39.456579,-107.756672
77° E

Photo 5. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321

Inspection Photos

Location Name: ROSE RANCH-67S93W/10SWSE

Location ID: 334675



Photo 6. Photo shows interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801321