

Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334583

Location Name: PARKER RANCH-67S93W/15NWNW

Inspection Document #: 702801323

Garfield County, CO

NWNW Section 15 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PARKER RANCH-67S93W/15NWNW

Location ID: 334583



Photo 1. Photo taken from the entrance shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801323

Inspection Photos
Location Name: PARKER RANCH-67S93W/15NWNW
Location ID: 334583



+39.45

3/3/23
+39.450191,-107.765758
34° NE



Photo 2. Photos show production areas. A tank battery sign is absent (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801323

Inspection Photos

Location Name: PARKER RANCH-67S93W/15NWNW

Location ID: 334583



Photo 3. Photo shows interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801323