

Inspection Photos
Location Name: SRC Pratt 33-29D
Location ID: 319203

Mar 6, 2023 at 12:52:31 PM
40.017588,-105.022622
Veld County
COGCC



Pic 1 wellheads, fence needs to be repaired/put back together.

Mar 6, 2023 at 12:53:57 PM
40.013447,-105.029864
Veld County
COGCC



Pic 2 tanks

Inspection Photos
Location Name: SRC Pratt 33-29D
Location ID: 319203

Mar 6, 2023 at 12:54:45 PM
40.017621,-105.022712
Veld County
COGCC



Pic 3 berm, on southeast side of tanks battery needs to be repaired.


Mar 6, 2023 at 12:55:25 PM
40.017669,-105.022600
Veld County
COGCC



Pic 4 ECD

Inspection Photos
Location Name: SRC Pratt 33-29D
Location ID: 319203

Mar 6, 2023 at 12:55:32 PM
40.017751,-105.022544
Veld County
COGCC




Pic 5 Separators

Mar 6, 2023 at 12:56:55 PM
40.017715,-105.022312
Veld County
COGCC




Pic 6 gas meter runs

Inspection Photos
Location Name: SRC Pratt 33-29D
Location ID: 319203



Pic 7 GMR flowlines appear to be open to sales line.



Pic 8 GMR flowlines appear to be open to sales lines.

Inspection Photos
Location Name: SRC Pratt 33-29D
Location ID: 319203

Mar 6, 2023 at 12:59:58 PM
40.016483,-105.021812
Veld County
COGCC



Pic 9 Separator is unused, and needs to be removed from location.