

# Inspection Photos

March 3, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334582

Location Name: ROSE RANCH-67S93W/15NENW

Inspection Document #: 702801327

Garfield County, CO

NENW Section 15 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ROSE RANCH-67S93W/15NENW

Location ID: 334582



3/3/23  
+39.451255,-107.761406  
234° SW

**Photo 1.** Photo taken from the east shows an overview of the location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801327

## Inspection Photos

Location Name: ROSE RANCH-67S93W/15NENW

Location ID: 334582



**Photo 2.** Photo shows piping at the tank battery is open ended/lacks wildlife protection BMPs.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801327

Inspection Photos  
Location Name: ROSE RANCH-67S93W/15NENW  
Location ID: 334582



**Photo 3.** Photos show production areas. Tank battery sign absent at northeastern battery (left).



## Inspection Photos

Location Name: ROSE RANCH-67S93W/15NENW

Location ID: 334582



**Photo 4.** Photos show production areas.

Inspection Photos  
Location Name: ROSE RANCH-67S93W/15NENW  
Location ID: 334582



**Photo 5.** Photo shows production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801327