

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335781

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 1: Sign installed at battery



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



March 6, 2023

Photo 2: Fence repaired.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 3: Photo example of areas where liner is separating from the metal containment berm.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 4: Photos 4-8 examples showing BMPs to stabilize, as well as to minimize tracking, degradation and sediment transport remain missing or insufficient on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 6: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 7: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335781



Photo 8: See comments under photo 4.

