

# Interim and Stormwater Inspection

February 28, 2023

Operator: Renegade Oil & Gas , #74165

Location ID: 320660

Inspection Document #:709400034

Arapahoe, CO

SESW, Section 28, 5S64W

Reed Wold

Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Par State 28-14/2

Location ID: 413721



Photo 1. Photo taken of location sign at location



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 709400034



Inspection Photos

Location Name: Par State 28-14/2

Location ID: 413721



**Photo 2** Photo taken of drainage ditch alongside access road ot site



**Photo 3.** See Photo 2 comments.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400034



Inspection Photos

Location Name: Par State 28-14/2

Location ID: 413721



**Photo 4.** Photo taken of culvert outlet on access road just prior to pad.



**Photo 5.** Photo of access road at culvert, sediment laden stormwater leaving site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 709400034