

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 1: Tank Battery Sign



Photo 2: Appears stained soil was removed

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 3: Equipment removed



Photo 4: Stained soil appears to be removed

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 5: Stained soil appears to be removed; Trash, unused equipment



Photo 6: Unused/disconnected equipment

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 7: Trash



Photo 7: Stained soil

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 8: Stained soil