

Inspection Photos

March 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 322426

Location Name: CLOUGH-66S94W/14NESE

Inspection Document #: 702801336

Garfield County, CO

NESE Section 14 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/14NESE
Location ID: 322426



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: CLOUGH-66S94W/14NESE
Location ID: 322426



Photo 2. Photos show production areas.



Inspection Photos

Location Name: CLOUGH-66S94W/14NESE

Location ID: 322426



Photo 3. Photos show rill erosion occurring adjacent to the access road.

Inspection Photos
Location Name: CLOUGH-66S94W/14NESE
Location ID: 322426



Photo 4. Photos show rill and gully erosion occurring adjacent to the access road.



Inspection Photos
Location Name: CLOUGH-66S94W/14NESE
Location ID: 322426



Photo 5. Photo shows an example of interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801336