

# Inspection Photos

March 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335065

Location Name: CLOUGH-66S94W/14SESE

Inspection Document #: 702801338

Garfield County, CO

SESE Section 14 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CLOUGH-66S94W/14SESE  
Location ID: 335065



**Photo 1.** Photos taken taken from the south show an overview of the location to the west (left) and east (right).



Inspection Photos  
Location Name: CLOUGH-66S94W/14SESE  
Location ID: 335065




Photo 2. Photos show production areas.



Inspection Photos  
Location Name: CLOUGH-66S94W/14SESE  
Location ID: 335065



**Photo 3.** Photo shows trash/debris (fence panels) at the southwest of the location.



Inspection Photos  
Location Name: CLOUGH-66S94W/14SESE  
Location ID: 335065



**Photo 4.** Photos show erosion degradation occurring on the slope to the north of the separators. Slopes are bare and unprotected. Only annual vegetation is present.

Inspection Photos  
Location Name: CLOUGH-66S94W/14SESE  
Location ID: 335065



**Photo 5.** Photos show interim areas to the east. Seeded perennial grasses are well established.

