

Inspection Photos

March 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324214

Location Name: CLOUGH-66S94W/14SWSE

Inspection Document #: 702801343

Garfield County, CO

SWSE Section 14 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/14SWSE
Location ID: 324214



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: CLOUGH-66S94W/14SWSE
Location ID: 324214



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801343

Inspection Photos
Location Name: CLOUGH-66S94W/14SWSE
Location ID: 324214



Photo 3. Photos show erosion degradation occurring on the slope at the northeast of the location. Slopes are bare and unprotected.

Inspection Photos
Location Name: CLOUGH-66S94W/14SWSE
Location ID: 324214



Photo 4. Photos show degradation to the pad surface. Degraded pad is acting as a sediment source. Note sediment laden stormwater within ruts (left) and sediment from degraded pad flowing off location (right). Arrow indicates area of ruts shown in left photo.

Inspection Photos
Location Name: CLOUGH-66S94W/14SWSE
Location ID: 324214



Photo 5. Photo shows an example of interim area vegetation. Native shrubs are established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801343