

Construction and Stormwater Inspection

Date: 03/03/2023

Operator: ST CROIX OPERATING INC - 81490

Location ID: 474453

Inspection Document #: 708200022

Washington County, CO

NESW Section 22 T2N R49W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Alice Seedorf 1
Location ID: 474453



Photo 1. Facing south near the location's entrance. The perimeter berm BMP consists of unconsolidated material and need to be repaired/maintained until final reclamation is achieved pursuant to Rule 1004. Staff acknowledges that soil moisture and weather may delay maintenance; it is Staff's expectation that the BMPs are addressed as soon as conditions permit. Until then, the location will remain out of compliance with Rule 1002.f.(2).

Inspection Photos
Location Name: Alice Seedorf 1
Location ID: 474453




Photo 2. Facing west from the southeast corner of the location. See comments in Photo 1.

Inspection Photos
Location Name: Alice Seedorf 1
Location ID: 474453



Photo 3. Facing north from the southwest corner of the location. See comments in Photo 1.

Inspection Photos
Location Name: Alice Seedorf 1
Location ID: 474453



Photo 4. Facing west from the northeast corner of the location. See comments in Photo 1.

Inspection Photos
Location Name: Alice Seedorf 1
Location ID: 474453



Photos 5 & 6. Facing south near the topsoil stockpile. Photo illustrates stained soil that will need to be properly cleaned up.