

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL 23-4D Pad

Location ID: 335778



Photo # 1984 From entrance to location



Photo # 1985 From entrance to location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL 23-4D Pad

Location ID: 335778



Photo # 1986 From entrance to location



Photo # 1988 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL 23-4D Pad

Location ID: 335778



Photo # 1989 Location



Photo # 1992 Flowline heating insulation open ended



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL 23-4D Pad

Location ID: 335778



**Photo # 1997 Open ended load line, unused equipment & hole in containment liner**



**Photo # 1995 Containment liner needs maintenance**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL 23-4D Pad

Location ID: 335778



Photo # 1996 Containment liner needs maintenance



Photo # 1993 Battery signage weathered & illegible



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources