

# Inspection Photos

API: 071-08757

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 2.** There is a produced water leak bubbling up near the wellhead at the red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 3.** There is stained soil around the wellhead that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 4.** The water leak is flowing across the location toward the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 5.** Facing northwest at the location showing spread of water leak across the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 6.** Facing southeast at the location showing spread of water leak across the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023

## Inspection Photos



**Photo 7.** Facing toward the southwest cut slope. Soils were pushed out to allow better drainage however loose soils pushed out need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08757 | Date: 3/9/2023