

Inspection Photos

API: 071-09369

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 1. Facing east toward the location. There was a recent frac operation at the location. Observed a semi transporting the coil offsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 2. There is numerous areas of oil stained soil from the equipment parked on location which will need to be cleaned up ASAP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 3. There is oily fluid sprayed out at the onto the ground and engine panels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 4. The pit liner and fence are degraded and not maintained.



Inspection Photos



Photo 5. There is frac sand spilled out over the ground that was not properly handled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 6. Facing toward south side of the location where frac sand was spill out on the ground approximately 70' x 30' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 7. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023

Inspection Photos



Photo 8. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09369 | Date: 3/9/2023