

# Inspection Photos

API: 071-09386

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 1.** Facing toward the switch back of the access road. There is erosion beginning to occur in this area which should be addressed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 2.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 3.** Sign is posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 4.** Facing toward the wellhead. There is a slight water leak at wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 5.** Facing northeast toward the pit. The pit liner is torn and degraded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 6.** Facing southeast toward the pit. The pit liner is torn and degraded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023

## Inspection Photos



**Photo 7.** Facing west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09386 | Date: 3/9/2023