

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2013 From entrance to location



Photo # 2014 From entrance to location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2015 From entrance to location



Photo # 2016 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Mar 8, 2023 at 2:31:45 PM

Photo # 2018 Location



Mar 8, 2023 at 2:33:39 PM

Photo # 2019 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2020 Flowline heating insulation open ended



Photo # 2022 Containment needs maintenance



## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618




Photo # 2023 Containment needs maintenance



Photo # 2024 Containment needs maintenance

## Inspection Photos

Location Name: CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad

Location # 335618



Photo # 2025 Containment needs maintenance