

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Photo 1 – Pumping Units

Photo 2 – Pumping Units

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925




Photo 3 – Unused Pumping Unit at 3-17 Wellsite

Photo 4 – Well Sign

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Photo 5 – ECDs and Flare



Photo 6 – North Treater

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Photo 7 – NW Corner of Berm – Stained Soil

Photo 8 – NW Corner of Berm – Stained Soil

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Colorado Oil and Gas Conservation Commission
40.74332, -104.12076, 4975.3ft, 283°
03/08/2023 13:25:33



Colorado Oil and Gas Conservation Commission
40.743, -104.12041, 4970.0ft, 300°
03/08/2023 13:26:28

Photo 9 – NW Corner of Berm – Stained Soil

Photo 10 – South Treater

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Colorado Oil and Gas Conservation Commission
40.7429, -104.12017, 4959.0ft, 271°
03/08/2023 13:27:28



Colorado Oil and Gas Conservation Commission
40.74291, -104.12017, 4961.7ft, 278°
03/08/2023 13:27:34

Photo 11 – Stained Soil

Photo 12 – Stained Soil

Inspection Photos
Location Name: Nelson 2-17-9-60 PAD
Location ID: 431925



Photo 13 – Stained Soil

Photo 14 – Stained Soil