

Inspection Photos
Location Name: Varra 12-9-66
Location ID: 423403



Photo 1: Tank Battery Sign



Photo 2: BBLs installed

Inspection Photos
Location Name: Varra 12-9-66
Location ID: 423403



Photo 3: unused/disconnected equipment, trash



Photo 4: unused/disconnected equipment, trash

Inspection Photos
Location Name: Varra 12-9-66
Location ID: 423403



Photo 5: Stained soil



Photo 6: Stained soil