

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Location – Photo #01266




Wellhead – Photo #01267

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Separators – Photo #01269



Tank Battery – Photo #01272




LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Berm Wall Damage – Photo #01274



Slope Erosion – Photo #01279

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Unprotected Soil Stockpiles – Photo #01281



Lack of Stabilization/Soil Stockpile – Photo #01277

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Inadequate Tracking BMP – Photo #01288