

Inspection Photos

Location Name: Yellow Creek Federal #1-41-1 & Spill/Release

Location ID: #316655 & Spill/Release ID: #483942

Inspection Date: March 7, 2023



Photo #1 – Overview of valve can (Point of Release) and tank battery from northwest.



Photo #2 – View of tank battery from northwest. Note filter pot in northwest corner of tank battery.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal #1-41-1 & Spill/Release

Location ID: #316655 & Spill/Release ID: #483942

Inspection Date: March 7, 2023



Photo #3 – Filter pot secondary containment device was filled with fluids (commingled hydrocarbons and snowmelt) during inspection.



Photo #4 – Localized accumulation of oily waste (hydrocarbon-impacted snow and soil) outside of tank battery and filter pot secondary containment on north side (1).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal #1-41-1 & Spill/Release

Location ID: #316655 & Spill/Release ID: #483942

Inspection Date: March 7, 2023



Photo #5 - Localized accumulation of oily waste (hydrocarbon-impacted snow and soil) outside of tank battery and filter pot secondary containment on north side (2).



Photo #6 – A filter sock had fallen from its storage area into tank battery secondary containment on inspection date. Due to likelihood of high winds in the area, it is recommended that the Operator utilize a dedicated storage container to prevent loss of unused equipment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal #1-41-1 & Spill/Release

Location ID: #316655 & Spill/Release ID: #483942

Inspection Date: March 7, 2023



Photo #7 – Check dam inside of impacted intermittent drainage.



Photo #8 – Overview of access area adjacent to impacted drainage.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Yellow Creek Federal #1-41-1 & Spill/Release

Location ID: #316655 & Spill/Release ID: #483942

Inspection Date: March 7, 2023



Photo #9 – Volume labels and NFPA placards on several tanks in need of repair.

