

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 03/07/2023 Document Number: 403160492

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10330 Contact Person: Brent Bongers Company Name: INVESTMENT EQUIPMENT LLC Phone: (361) 935-5633 Address: PMB 412 558 CASTLE PINES PKWY Fax: () City: CASTLE PINES State: CO Zip: 80108 Email: bbongers@vedolaresources.com

Identification Information

API Number: 05 - - OGCC Facility ID: 107546 Initial Form 19 or 27 Document number: Facility Name: DAVIS 1 Facility Number: Facility Type: PIT Location QtrQtr: SWNE Section: 30 Township: 3S Range: 51W Meridian: 6 County: WASHINGTON Field Name: RANGER Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc. Agent Name: Drezden Kinnaird Title: Project Manager Phone Number: 970-493-7780 Email: dkinnaird@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 07/07/2022 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 771019 Facility Name: Davis 1 Facility Type: Oil/Gas Production Facility Location: QtrQtr: SWNE Sec: 30 Twp: 3S Range: 51W Meridian: 6 County Name: WASHINGTON Latitude: 39.764836 Longitude: -103.128136

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 108278 Document Name: EDD1 File Name: Davis EDD.xls SampleType: Matrix: Facility ID: 771019 Sample ID: 646857 Sample Name: IE_DAVIS_316969 Sample Date: 08/26/2022 Collection Point: PitDis Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: 24643 Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Summit Scientific Lab Sample ID: 2207082-02

Batch ID: 108279 Document Name: EDD2 File Name: 2207082F-01 - Impetro 909.j.xls

SampleType: _____ Matrix: _____

Facility ID: 771019 Sample ID: 646858 Sample Name: IE_DAVIS_316969 Sample Date: 07/07/2022

Collection Point: PitDis Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: 24643 Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Summit Scientific Lab Sample ID: 2207082-01

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
771019	403339178	2207082F - Impetro 909.j..pdf	Analytical Laboratory Report	PDF
771019	403339179	2022_0707_Davis 1_Field Data.pdf	Field Data Report	PDF
316969	403160499	2022_0707_Davis 1_Field Data.pdf	Field Data Report	PDF
316969	403160500	2207082 - Impetro 909.j..pdf	Analytical Laboratory Report	PDF
771019	403339160	2022_0707_Davis 1_Field Data.pdf	Field Data Report	PDF
771019	403339161	2207082F - Impetro 909.j..pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
646857	121-05369	DAVIS W T 2	
646857	121-05373	DAVIS W T 3	
646857	121-05413	DAVIS W T 1	
646858	121-05369	DAVIS W T 2	
646858	121-05373	DAVIS W T 3	
646858	121-05413	DAVIS W T 1	

General Comments

User Group	Comment	Comment Date
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/13/2023
Environmental	RTD - Sample Facility ID, Collection Point.	02/28/2023

Total: 2 comment(s)