

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

03/13/2023

Document Number:

403131199

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10690 Contact Person: Brent Bongers
Company Name: IMPETRO RESOURCES LLC Phone: (361) 935-5633
Address: 558 CASTLE PINES PKWY UNIT B-4 Fax: ()
City: CASTLE PINES State: CO Zip: 80108 Email: bbongers@vedolaresources.com

Identification Information

API Number: 05 - - OGCC Facility ID: 102627 Initial Form 19 or 27 Document number:
Facility Name: CHANDLER 2-15 Facility Number: Facility Type: PIT
Location QtrQtr: NWNE Section: 15 Township: 2N Range: 49W Meridian: 6
County: WASHINGTON Field Name: HIGH POCKETS
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc. Agent Name: Drezden Kinnaird Title: Project Manager
Phone Number: 970-493-7780 Email: dkinnaird@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 07/06/2022

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 237708 Facility Name: CHANDLER 2-15 Facility Type:
Location: QtrQtr: NWNE Sec: 15 Twp: 2N Range: 49W Meridian: 6
County Name: WASHINGTON Latitude: 40.145840 Longitude: -102.840590

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 108448 Document Name: EDD File Name: 2207126.xml
SampleType: Matrix:
Facility ID: 237708 Sample ID: 647043 Sample Name: IR_Chandler_317278 Sample Date: 07/06/2022
Collection Point: PitDis Matrix: WATER Pre Post: Rule 909.j initial sample
Project Number: 24643 Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ALS Lab Sample ID: 2207126-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
102628	403250150	2207126_Summary.pdf	Analytical Laboratory Report	PDF

237708	403344381	2207126_Summary.pdf	Analytical Laboratory Report	PDF
701420	403131215	20220706_144459.jpg	Photographs	JPG
102628	403250152	2022_0706_Chandler_Pit Sampling Picture_Field Data.pdf	Field Data Report	PDF
701420	403131213	2207126_Summary.pdf	Analytical Laboratory Report	PDF
701420	403131211	2022_0706_Chandler_Pit Sampling Picture_Field Data.pdf	Field Data Report	PDF

Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
647043	121-10211	CHANDLER 2-15	

General Comments

User Group	Comment	Comment Date
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/14/2023
Environmental	RTD-Facility ID, Collection Point	01/31/2023
Environmental	Returned to Draft for correction. Incorrect Facility ID.	12/02/2022
Total: 3 comment(s)		