

# Interim Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 429231

Inspection Document #: 708200045

Weld County, CO

NENE Section 1 T7N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Green 1-7 Facility  
Location ID: 429231



**Photo 1.** Facing east at the northwest-most tank battery. Unknown fluid observed around bottom of tank. The tank itself will need to be inspected per Rule 609.b and the stained soil will need to be disposed of per Rule 905.e.

Inspection Photos  
Location Name: Green 1-7 Facility  
Location ID: 429231



**Photo 2.** Facing south at pit. Netting is inadequate with large opening observed.

Inspection Photos  
Location Name: Green 1-7 Facility  
Location ID: 429231



**Photo 3.** Facing southwest at pit. Hydrocarbons observed within the pit will need to be properly cleaned up and disposed of per Rule 909.d.

Inspection Photos  
Location Name: Green 1-7 Facility  
Location ID: 429231



**Photo 4.** Facing southeast near pit. It appears this equipment/water truck has been parked for an extended period of time. Locations are not to be used for equipment storage.

Inspection Photos  
Location Name: Green 1-7 Facility  
Location ID: 429231



**Photo 5.** Google Earth aerial imagery taken circa 09/2019, illustrating the water truck has been parked on location for an extended period of time.