

Interim Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 427041

Inspection Document #: 708200030

Weld County, CO

Lot 1 Section 2 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 1. Facing southwest at flare and combustor. Tumbleweed accumulations were observed in and around equipment and are now considered debris as they present a fire hazard.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 2. Facing northeast at pump jack, see comments in Photo 1.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 3. Oily waste/stained soil near wellhead.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 4. Facing east from the southwest corner of the interim area. Non-uniform vegetation cover resulting in bare soil and undesirable vegetation (e.g. russian thistle and kochia) were observed throughout the location.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 5. Facing north near pump jack, see comments in Photo 4.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 6. Facing north near pump jack, in the interim area. It appears that only a portion of the interim area has been managed for undesirable vegetation. See comments in Photo 4 for additional.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 7. Facing northeast from southern portion of interim area; see comments in Photos 4 and 6.

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 8. Facing north from the center portion of the location, see comments in Photo 4.