

# Interim Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 331563

Inspection Document #: 708200032

Weld County, CO

SESE Section 36 T8N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: State 68N60W  
Location ID: 331563



**Photo 1.** Facing northeast from the former tank battery. Photo illustrates that tanks and other equipment have been removed, however, unmarked risers and piping were still in place and need to be removed.

Inspection Photos  
Location Name: State 68N60W  
Location ID: 331563



Photo 2. See comments in Photo 1.

Inspection Photos  
Location Name: State 68N60W  
Location ID: 331563



Photo 3. See comments in Photo 1.

Inspection Photos  
Location Name: State 68N60W  
Location ID: 331563



**Photo 4.** Facing northeast from the location, near the former pit location. Rill erosion was occurring on the pad surface and appeared to be moving off location. Snow cover prevented full observation of the stormwater travel and any BMPs that may or may not be in place to prevent stormwater from exiting off location. The working pad will need to be stabilized to prevent further erosion.

Inspection Photos  
Location Name: State 68N60W  
Location ID: 331563



**Photo 5.** Facing southwest near the former pit location. See comments in Photo 4.