

LARAMIE ENERGY LLC, Homer Deep Unit/9-11

Location # 432255



Location/Lack of Stabilization – Photo #01381



Wellhead – Photo #01382

LARAMIE ENERGY LLC, Homer Deep Unit/9-11

Location # 432255



Separators– Photo #01388



Tank Battery – Photo #01390

LARAMIE ENERGY LLC, Homer Deep Unit/9-11

Location # 432255



Gas Meter – Photo #01385



Stained Soil – Photo #01389

LARAMIE ENERGY LLC, Homer Deep Unit/9-11

Location # 432255



Weeds – Photo #01384



Weeds/Slope Erosion – Photo #01391