

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 14-29A Pad

Location ID: 323922



Photo # 2294 From entrance to location



Photo # 2295 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 14-29A Pad

Location ID: 323922



Photo # 2296 Location



Photo # 2297 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 14-29A Pad

Location ID: 323922




Photo # 2298 Location



Photo # 2300 Calibration info not conspicuously posted