

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



Photo # 2304 From entrance to location



Photo # 2305 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



Photo # 2306 Location



Photo # 2308 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



Photo # 2309 Location



Photo # 2311 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



Photo # 2312 Containment needs maintenance



Photo # 2313 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



Photo # 2316 Calibration info not conspicuously posted

Photo # 2317 Calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 62-29 Pad

Location ID: 335252



**Access entrance CA photo from Inspection # 700704653
conducted on 10/27/2022**



Photo # 2322 Entrance to access road