

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334582

Location Name: ROSE RANCH-67S93W/15NENW

Inspection Document #: 702801347

Garfield County, CO

NENW Section 15 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: ROSE RANCH-67S93W/15NENW

Location ID: 334582



**Photo 1.** Photos show a cap has been installed on piping at the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801347