

# Inspection Photos

API: 025-06022

Operator: GRAND MESA OPERATING CO

Inspection Date: 3/14/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 1.** Facing southwest at Lat/Long:38.34638,-103.63420. This area has eroded and culvert is not functioning properly and should be removed or repaired..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 2.** Facing east at Lat/Long:38.34369,-103.63626.



**Photo 3.** There are rocks piled up in front of the culvert which will impede water flow.



## Inspection Photos



**Photo 4.** Facing southeast at Lat/Long:38.34370,-103.638545. This culvert has completely washed out and should be removed or repaired. A dry crossing may be more appropriate at this area due to frequent flooding.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 5.** Facing southwest along the access road. The access road is bare of vegetation and needs to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 6.** Facing southwest toward the fenced location. The access road is bare of vegetation and needs to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 7.** Center of the location facing northeast. The location consists mostly of undesirable weeds and bare soil. Reseeding needs to be performed.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 8.** Center of the location facing northwest.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 9.** Center of the location facing southwest.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 10.** Center of the location facing southeast.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 11.** View of groundcover shows no desirable vegetation growth and mostly bare grounds with some undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023

## Inspection Photos



**Photo 12.** Facing northeast towards the reference area which consists of a uniform perennial vegetation cover of Blue grama, Sand drop seed, Alkali sacatan, among other native species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06022 | Date: 3/14/2023