

Interim Reclamation and Stormwater Inspection

March 9, 2023

Operator: CONFLUENCE DJ LLC #10518

Location ID: 454560

Inspection Document #: 697504561

Weld County, CO

SWSW Section 3 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 70 Ranch/10 West
Location ID: 454560



Photo 1. Photo taken from the southern location, facing East. Photo illustrates weed establishment and weed maintenance needed along the southern perimeter.



Photo 2. Photo taken from the southeastern location, facing North. Photo illustrates the Operator has seeded stormwater BMP area (berm and ditch). Desirable germination was observed and in process of establishment. See Photo 3.

Inspection Photos
Location Name: 70 Ranch/10 West
Location ID: 454560



Photo 3. Close up photo illustrating desirable vegetation.



Photo 4. Photo taken from the northeastern location, facing North. Photo illustrates the Operator has performed interim reclamation. Desirable germination was observed and in process of establishment.

Inspection Photos
Location Name: 70 Ranch/10 West
Location ID: 454560



Photo 5. Photo taken from the northeastern location, facing Northwest. See comments under Photo 4.



Photo 6. Photo taken from the northwestern location, facing North. See comments under Photo 4.

Inspection Photos
Location Name: 70 Ranch/10 West
Location ID: 454560



Photo 7. Photo taken from the northwestern location, facing West. See comments under Photo 4.



Photo 8. Photo taken from the western location, facing West. Photo illustrates concrete waste within rip rap of the culvert.

CDPHE is addressing this observation.