

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334944

Location Name: BENZEL-66S93W/36SESW

Inspection Document #: 702801346

Garfield County, CO

SESW Section 36 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334944



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334944



**Photo 2.** Photo shows open pipes at the tank battery lack wildlife protection BMPs.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801346







Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334944



**Photo 4.** Photos show staining behind the separator for well API #045-07462.