


Caerus Piceance LLC

Love Ranch Fee 1

Location #316151



Sign at lease road entrance



From entrance to location



Caerus Piceance LLC
Love Ranch Fee 1
Location #316151



Debris



Debris



Caerus Piceance LLC
Love Ranch Fee 1
Location #316151



Debris



Debris

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Debris



Debris

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Equipment container on location



Equipment storage on location

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**




Unused equipment



Lack of maintenance, catch can full

Caerus Piceance LLC
Love Ranch Fee 1
Location #316151




Debris



Debris

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Debris



Debris



**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Out of service tank battery



Tank battery out of service. No maintenance.

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Tanks out of service



Tanks out of service

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Water exiting location causing erosion



Water exiting location causing erosion

**Caerus Piceance LLC
Love Ranch Fee 1
Location #316151**



Berm BMP not maintained



Water leaving location causing erosion