

Location #336042



Entrance to location signage



From entrance to location

**Caerus Piceance LLC
Freedom Unit – 62S97W/16SWNW
Location #336042**



From location toward meter manifold and separators



Bulk and test separator building

**Caerus Piceance LLC
Freedom Unit – 62S97W/16SWNW
Location #336042**



Catch tank cover not properly installed



No Stormwater BMP's around location

**Caerus Piceance LLC
Freedom Unit – 62S97W/16SWNW
Location #336042**



**Stormwater flow from location, down lease road,
across and off Love Ranch Fee #5 location**



Lease road erosion onto another location