



00229524

RECEIVED

NOV 23 1984

COLO. OIL & GAS CONS. COMM.

STATE PLUGGING REPORTJ. W. GIBSON WELL SERVICE COMPANY

Well Name

Tolly # 16-7

Location

SE/SE Sec 7 35 55W

Operator

Oscot oil Corp.This well was filled with Wt. 10 Mud.25 sacks were put @ 4954.25 sacks were put at the bottom of surface pipe and10 sacks at the top of the surface pipe.☒ YES ☐ NO Steel cap was put on surface casing.

To my knowledge, no junk was left in the hole.

Remarks: _____

Plugging orders were received from McLear 2:15 A.M.

Signed,

J. W. GIBSON WELL SERVICE COMPANY

John Kuyt.TIME: 10:15 ☒ A.M. ☐ P.M.DATE: 11/6/84