

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

07/22/2022

Document Number:

403113938

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

### Uses of Ground Water Sampling Form

Submit a New Water Quality Sample Location to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

Submit a New Water Quality Sample to the COGCC for rules 317B, 318A.5, 608, 609.d(3)., Condition of approval, or other reason.

### Operator Information

OGCC Operator Number: 10758 Contact Person: Sam Bollinger  
Company Name: OGRIS OPERATING LLC Phone: (719) 680-0808  
Address: PO BOX 53467 Fax: ( )  
City: MIDLAND State: TX Zip: 79710 Email: sbollinger@ogrisop.com

### Well/Facility Information

API Number: 05 - - OGCC Facility ID: 292548  
Well/Facility Name: HILL RANCH Well/Facility Number: 15-09  
Location QtrQtr: NESE Section: 15 Township: 35S Range: 67W Meridian: 6  
County: LAS ANIMAS Field Name: PURGATOIRE RIVER  
Federal, Indian or State Lease Number:

### Information Submitted By:

Company Name: Ogris Operating, LLC Agent Name: Sam Bollinger Title: Environmental Coordinator  
Phone Number: 719-680-0808 Email: sbollinger@ogrisop.com

### Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 279160 Facility Name: HILL RANCH 15-09 Facility Type: Oil and Gas Well  
Location: QtrQtr: NESE Sec: 15 Twp: 35S Range: 67W Meridian: 6  
County Name: LAS ANIMAS Latitude: 36.994962 Longitude: -104.867747

### Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 100815 Document Name: Size of file in bytes: 27238 File Name: HR 15-09 EDD RAD.xlsx  
SampleType: Matrix:  
Facility ID: 279160 Sample ID: 638436 Sample Name: HR 15-09 Radium Sample Date: 05/18/2022  
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Lab Sample ID: 2205-249-01

Batch ID: 100814 Document Name: Size of file in bytes: 144384 File Name: HR 15-09 EDD.xls  
SampleType: Matrix:  
Facility ID: 279160 Sample ID: 638435 Sample Name: HR 15-09 Sample Date: 05/18/2022  
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2205249-01

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
279160	403113948	Pit inspection report HR 15-09.xlsx	Field Data Report	XLSX
279160	403113944	2205249 GAL FINAL 06 22 22 1409.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/16/2023
Total: 1 comment(s)		