

Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334602

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Inspection Document #: 702801360

Garfield County, CO

NWSE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 1. Photos show an overview of the location to the south (left) and north (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801360

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 2. Photos show stained gravel in secondary containment below spilled produced water/condensate tank # 81396.