

# Inspection Photos

March 14, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335442

Location Name: BBC-66S92W/23SENE

Inspection Document #: 702801366

Garfield County, CO

SENE Section 23 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 1.** Photo taken from the entrance shows an overview of the location.





Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 2.** Photos show bubbles rising in the area of a separator and flowline.



Inspection Photos  
Location Name: BBC-66S92W/23SENE  
Location ID: 335442



**Photo 3.** Photos show recently disturbed soils. The working pad is not stabilized.