

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334839

Location Name: COUEY-67S92W/8NWNW

Inspection Document #: 702801368

Garfield County, CO

NWNW Section 8 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: COUEY-67S92W/8NWNW  
Location ID: 334839



**Photo 1.** Photos show the tank battery. A tank battery sign is present. A bull plug is installed on the tank drain line.



Inspection Photos  
Location Name: COUEY-67S92W/8NWNW  
Location ID: 334839



**Photo 2.** Photo shows an unmarked anchor at the northeast of the location.